

BRADLEY Motorworks Inc.

dba FordCummins.com
 220 Lost Creek Dr.
 Kalispell, MT 59901



Estimate

Date	Estimate #
7/5/2010	FCPN 1259

Name / Address
Happy Customer 2B On The Rd. Anywhere, -- _____



Description	Qty	FC PART#	Total
Truck: 2002 Ford Super Duty Engine was: 7.3 PowerStroke Transmission is: Automatic 4R100 Cummins engine going in: 24 valve Cummins (1998-2002)			
ADAPTER PLATE: 94C-7.3*	1	1319	699.00
Torque Converter Adapter Setup*	1	1169	325.00
TRANS. CONTROLLER & HARNESS - PCS- 4R100	1	1317	850.00
TRANS. HARNESS PREP (4R10), CONTROLLER PRE-PROGRAMMING, & TECH SUPPORT	1	1408	100.00
MOUNT SET-SUPER DUTY-12V/24V*	1	1037	295.00
ALTERNATOR REGULATOR KIT:To Regulate Dodge Alternator	1	1026	60.00
BUSHING KIT: [99-02 7.3] Water Temperature Sensor Adapter, Oil Pressure Sensor Adaptor, 3/8" Compression Coupler*	1	1054	30.00
Wiring Instructions-24V	1	1052	15.00
INSTALLATION MANUAL 99+ SUPER DUTY	1	1075	0.00
EXHAUST MANIFOLD-98-02 24V Cummins (This moves the turbo away from the A/C box on the fire wall and provides about 6" of clearance)	1	1065	165.00
EXHAUST MANIFOLD/TURBO GASKET SET- 98.5 and newer	1	1397	20.00
TURBO OIL DRAIN TUBE-Flexible	1	1301	35.00
Turbo Elbows (Hx35)	1	1413	80.00
Turbo Elbow Flange (Hx35)	1	1338	75.00
Turbo Elbow Clamp (Hx35)	1	1345	35.00
A/C MANIFOLD (The suction discharge hose that bolts onto the back of the '94 or newer Dodge A/C pump...this will be crimped together with the Ford A/C lines.)	1	1027	131.00
AIR INTAKE KIT -99-03 FORD that had a 7.3 DIESEL (this puts the filter where the passenger side battery in the diesel currently sits, right behind the headlight, to obtain good fresh air) [with this kit in your truck you will use the existing rubber "dog-leg" to connect to the turbo]	1	1288	130.00
Always refer to web site fordcummins.com for current pricing.	Total		

BRADLEY Motorworks Inc.
 dba FordCummins.com
 220 Lost Creek Dr.
 Kalispell, MT 59901



Estimate

Date	Estimate #
7/5/2010	FCPN 1259

Name / Address
Happy Customer 2B On The Rd. Anywhere, -- _____



Description	Qty	FC PART#	Total
TACH SENSOR	1	1032	80.00
TACH MOUNT-1044*	1	1044	49.00
TACH BASE: For tach mount 1044 on 12V & 24V to read off of harmonic balancer	1	1177	49.00
TACH RING-1196 (for '89-'02 5.9 Cummins replacing a '94-'97 Ford 7.3 Powerstroke diesel engine)*	1	1196	125.00
Radiator hose kit (includes lower hoses, special connector pipe, upper radiator hose, and 8 worm drive hose clamps)	1	Misc	99.00
*NOTE: You will also need to replace your Ford electronic throttle pedal with a gas version throttle pedal.			
*NOTE: You will also need to use a cruise control servo and cable from a gas version Ford.			
Always refer to web site fordcummins.com for current pricing.		Total	\$3,447.00